

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Abstract

A multichambered boat that is constructed upside-down on stationary platforms where flotation chambers are located in the perimeter portion of the multichambered boat. The perimeter
5 chambers have a laterally downward sloping exterior surface that directs fluid downwardly and provides lift to the multichambered boat which creates a smoother ride. A fuel input line that passes through the flotation chamber to the fuel storage tank to provide convenient access for refueling the multichambered boat.